

25X1A

ORIG:

UNIT:

EXT:

DATE:

12 OCT 71

ROUTING

FILE NUMBER

Approved For Release 2002/10/16 : CIA-RDP74B00496R000400010027-5

C-311-C

Comments regarding reference(s)

205

1	D/M	8	RB	11		16		21	
2	D/M	7	D/O	12		17		22	
3	D/M	8	INTEL	13		18		23	
4	D/M	9	SAS	14		19		24	
5	D/SA	10	INTEL	15		20		25	

(classification)

SECRET

(date and time filed)

12 17 02 02 OCT 71

(elite)

(reference number)

(elite)

(reference number)

CITE

6133

25X1A

TO

PRIORITY

[redacted]

25X1A

25X1

25X1A

REF: [redacted]

SUBJ: HSN C-311-C LONG SHAFT

## 1. PLS ANSWER FOLLOWING QUESTIONS:

- A. WAS ANTIFUNGUS COATING WHICH CAUSED PROBLEMS APPLIED AT VENDOR PLANT OR IN FIELD?
- B. DID PRE-FLIGHT INDICATE SYSTEM OPERATING CORRECTLY?
- C. ANY THOUGHTS AS TO WHY THIS DEFICIENCY DID NOT SHOW UP DURING LOCK-OUT AND TEST FLIGHTS.

END OF MESSAGE

8  
2  
3  
2  
1

25X1A

AUTENTICATING OFFICER

COORDINATING OFFICERS

SECRET

Order 1  
Subject from original  
transcribing and  
translatingD/M/OSA  
RELEASING OFFICER